MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

AXLE DRIVE PINION TOOL — SERVICE MANUAL CORRECTION

NO.	TSB-91-27-004
DATE	February, 1991
MODEL	1988-91 Montero, Truck

TSB Revision TSB-91-27-004

PURPOSE

This bulletin corrects a part number error for one of the special tools used to install the front or rear axle drive pinion in 1988, 1989, 1990 and 1991 Montero and Truck models.

As reference to this bulletin, please write the TSB number in the boxes at the bottoms of the affected pages listed in the next paragraph, and write-in the correct tool number on the illustrations as shown below.

SERVICE MANUALS AFFECTED

1988 Montero Service Manual, Page 2-10, 2-80, 3-13, 3-48
1988 Truck Service Manual, Page 2-11, 2-91, 3-10, 3-42
1989 Montero Service Manual, Page 2-9, 2-62, 3-7, 3-34
1989 Truck Service Manual, Page 2-9, 2-73, 3-6, 3-28
1990 Montero Service Manual, Page 26-7, 26-46, 27-7, 27-33
1990 Truck Service Manual, Page 26-7, 26-42, 27-6, 27-26
1991 Truck Service Manual, Page 26-7, 26-42, 27-6, 27-26

CORRECTION

The Differential Seal Installer tool number, shown in the service manuals as MB990031-01, is incorrect. The correct tool number is **MB991168-01**.

The handle tool number, MIT304180, is correct.



~~MB990031-01~~ MIT991168-01 Drive pinion oil seal installer



023799

FILE UNDER:
Group 27 Rear Axle in the Dealer Service Information Binder (831)

CIRCULATE TO:

☐ SERVICE ADVISOR	☑ SERVICE MANAGER	☐ WARRANTY PROCESSOR	☐ SALES MANAGER
☐ GENERAL MANAGER	☐ PARTS MANAGER	☑ TECHNICIAN	

MSSF 0096-01